Application No. 10/564,923
Paper Dated: February 13, 2008
In Reply to USPTO Correspondence of November 13, 2007
Attorney Docket No. 0702-060135

AMENDMENTS TO THE SPECIFICATION

Please replace the paragraph beginning at page 2, line 9 and ending at page 2, line 12 with the following paragraph:

--When the rod and the link are not connected anymore by the weld, the conveyor belt could buckle, which is also referred to [[has]] as tenting. This could then result in jamming of the conveyor belt causing damage to the complete system.--